FLIGHT PLAN & SITE SURVEY

ERNSTBERGER FIELD

November 12, 2026

IMPORTANT NOTICE

Please ensure you have received all required authorizations prior to flight. This Site Survey was created using RPAS Wilco. The user accepts all responsibility for the accuracy of the information.

Terms & Conditions: rpaswilco.com/#tnc

Mission Information

ERNSTBERGER FIELD

FLIGHT DETAILS

Reference No:	**MAAC-795-4966**
Project Name:	**THE HILLTOP FLYING FARMERS**
Pilot Name:	**MAAC**
Pilot Certificate:	
Mission Type:	**VLOS**
Flight Start:	**November 12, 2026 10:07 PM**
Flight End:	**November 12, 2026 11:07 PM**

LOCATION DETAILS

Flight Address:	**ERNSTBERGER FIELD**
Latitude:	**44° 9' 50.18" N (44.164)**
Longitude:	**77° 2' 21.73" W (-77.039)**
Field Elevation:	**394 ft MSL**
Altitude / Radius:	**400.0 ft / 926 m (0.5 nm)**
Classification:	**UNCONTROLLED**
FIR / Contact:	**CZYZ / 905-676-4509**

REPORT CONTENTS

Site Survey • Obstacles (if available) • Nearby Aerodromes • Canadian Aviation Regulations • GFA • Aerodrome Supplements • METAR & TAF • NOTAMs • CFS

Flight Map & MODEL Details

MISSION LOCATION SURVEY

FLIGHT AREA MAP




MISSION LOCATION DETAILS

ROLE	LATITUDE	LONGITUDE
MODEL	44° 9' 50.18" N 44.164	77° 2' 21.73" W -77.039
Pilot		
Payload Op.		
Observer		

Airspace Classification

MISSION LOCATION SURVEY

AIRSPACE MAP



OVERLYING AIRSPACES


Class	Name	Floor	Ceiling
E	Trenton, ON d) [TCA]	700AGL	17000MSL

NEAREST AERODROMES & DISTANCE FROM OPERATION

TYENDINAGA (MOHAWK) (CPU6 - AERODROME - Reg)	Lat: 44.185	Long: -77.108	5.925KM	3.199NM	NW
Operator: FIRST NATIONS TECHNICAL INSTITUTE: PHONE: 1-800-263-4220 ext 5006, PHONE: 613-885-1340, POST: UNKNOWN **FIR Contact:** 905-676-4509					
PICTON (GREENBUSH) (CGB3 - AERODROME - Reg)	Lat: 44.001	Long: -77.073	18.308KM	9.886NM	S
Operator: JEFF DOUGLASS: PHONE: 613-885-6917, POST: UNKNOWN **FIR Contact:** 905-676-4509					

TYENDINAGA (MOHAWK) ON CPU6

REF	N44 11 05 W77 06 28 3SW 13°W UTC-5(4) Elev 260' A5000
OPR	First Nations Technical Institute 1-800-263-4220 ext 5006, 613-885-1340 13-20Z‡ Mon-Fri exc hols Reg PPR exc MEDEVAC and emerg
PF	B-1 13-20Z‡ Mon-Fri exc hols C-2,5 D-3,4,6
FLT PLN FIC	London 866-WXBRIEF (Toll free within Canada) or 866-541-4104 (Toll free within Canada & USA)
SERVICES	4 (O/R), 5



RWY DATA RCR	Rwy 09/27 4270x144 ASPH Thld 09 displ 390'. Rwy 15/33 2575x144 ASPH Thld 15 displ 150'. Opr Ltd win maint
LIGHTING	09-(LO non-std, May-Nov), 27-(LO non-std, May-Nov)
COMM ATF	Mohawk UNICOM ltd hrs O/T tfc 123.5 5NM 3300 ASL
CAUTION	Extv bird activity Apr-Oct. Possibility of NORDO maint equip on rwys. Extv flt tng activity on and within 20NM of A/D.

PICTON (GREENBUSH) ON CGB3

REF	N44 00 04 W77 04 24 2.87 ESE 12°W (2014) UTC-5(4) Elev 460´ A5000
OPR	Jeff Douglass 613-885-6917 Reg PPR
PF	B-1 C-2,3,4,5 D-6
FLT PLN FIC	London 866-WXBRIEF (Toll free within Canada) or 866-541-4104 (Toll free within Canada & USA)
SERVICES FUEL	MOGAS PN Opr
RWY DATA	Rwy 05(049°)/23(229°) 1500x60 GRASS
RCR	Opr No win maint. Rwy soft in spring.
COMM ATF	tfc 123.2 5NM 3500 ASL
CAUTION	Runway slopes down Thld 23. Rwy narrows at mid-field to 50' to cross seasonal drainage ditch. Treeline nearest to hangar may cause mechanical turbulence.

