

FLIGHT PLAN & SITE SURVEY

FIELD - 47117-A BALLAM RD. CHILLIWACK, BC

September 30, 2026



IMPORTANT NOTICE

Please ensure you have received all required authorizations prior to flight. This Site Survey was created using RPAS Wilco. The user accepts all responsibility for the accuracy of the information.

Terms & Conditions: rpaswilco.com/#tnc

Mission Information

FIELD - 47117-A BALLAM RD. CHILLIWACK, BC

FLIGHT DETAILS

Reference No:	MAAC-469-4448
Project Name:	FRASER VALLEY R/C FLYERS
Pilot Name:	MAAC
Pilot Certificate:	
Mission Type:	VLOS
Flight Start:	September 30, 2026 11:37 PM
Flight End:	October 01, 2026 12:37 AM

LOCATION DETAILS

Flight Address:	FIELD - 47117-A BALLAM RD. CHILLIWACK, BC
Latitude:	49° 12' 45.36" N (49.213)
Longitude:	121° 55' 10.09" W (-121.919)
Field Elevation:	36 ft MSL
Altitude / Radius:	400.0 ft / 926.0 m (0.5 nm)
Classification:	UNCONTROLLED
FIR / Contact:	CZVR / 604-586-4500


REPORT CONTENTS

Site Survey • Obstacles (if available) • Nearby Aerodromes • Canadian Aviation Regulations • GFA • Aerodrome Supplements • METAR & TAF • NOTAMs • CFS

Flight Map & MODEL Details

MISSION LOCATION SURVEY

FLIGHT AREA MAP



MISSION LOCATION DETAILS

ROLE	LATITUDE	LONGITUDE
 MODEL	49° 12' 45.36" N 49.213	121° 55' 10.09" W -121.919
 Pilot		
 Payload Op.		
 Observer		

Airspace Classification

MISSION LOCATION SURVEY

AIRSPACE MAP



OVERLYING AIRSPACES

Class	Name	Floor	Ceiling
E	T645 Fixed RNAV Route	2200AGL	12500MSL
E	T800 Fixed RNAV Route	2200AGL	12500MSL
C	Vancouver, BC h) [TCA]	5500MSL	6500MSL
C	Vancouver, BC s) [TCA]	6500MSL	8500MSL
C	Vancouver, BC t) [TCA]	8500MSL	9500MSL
E	East Vancouver, BC [CAE]	9000MSL	12500MSL
C	Vancouver, BC u) [TCA]	9500MSL	12500MSL

NEAREST AERODROMES & DISTANCE FROM OPERATION

CHILLIWACK (CYCW - AERODROME - Cert)	Lat: 49.153	Long: -121.939	5.844KM	3.156NM	S
Operator: MAGNUM MANAGEMENT INCORPORATED: PHONE: 604-792-3430, POST: UNKNOWN FIR Contact: 604-586-4500					
HARRISON HOT SPRINGS (CAE7 - WATERDROME - Reg)	Lat: 49.305	Long: -121.787	13.111KM	7.079NM	NE
Operator: VILLAGE: PHONE: 604-796-2171, POST: UNKNOWN FIR Contact: 604-586-4500					


BRITISH COLUMBIA

AERODROME / FACILITY DIRECTORY

CHILLIWACK BC

CYCW

REF	N49 09 12 W121 56 21 Adj S 17°E (2012) UTC-8(7) Elev 32' VTA A5004 LO2 T1
OPR	Magnum Management Inc 604-792-3430 1600-2230Z± Mon-Fri Cert
PF	A-2 (15-03Z±), 7 C-3, 4, 5, 6 (17-01Z±)
FLT PLN	
FIC	Kamloops 866-WXBRIEF (Toll free within Canada) or 866-541-4101 (Toll free within Canada & USA)
WX	AUTO H24 (see COMM)
SERVICES	
FUEL	100LL, JA (Cardlock) JA-1 (by truck) 604-991-0078 1430-2330Z± Mon-Fri exc hols, O/T call out chg
S	1, 2, 3, 4, 5, 6
RWY DATA	Rwy 07(066°)/25(246°) 3986x75 ASPH Depression in rwy aprx 1000' fr Thld 25.
RWY CERT	Rwy 07/25 AGN II
APRON	Apron Main: Heli ops not auth
RCR	Opr 1600-2230Z± Mon-Fri Ltd win maint.
LIGHTING	07-(TE ME) P2 4°, 25-(TE ME) P2 4° ARCAL-122.7 type K
COMM	
MF	tfc 122.7 3NM 2000 ASL (CAR 602.98)
AUTO	122.975
PRO	Rgt hand circuits Rwy 07 (CAR 602.96). Procedures for crossing the southern Strait of Georgia within Tml Class C airspace refer to Vancouver Intl, VTPC for Crossing the Southern Strait of Georgia. Tkof and ldg in grass area adj rwy by fixed-wing acft not auth.



CANADA WATER AERODROME SUPPLEMENT


Effective 0901Z 19 March 2026 to 0901Z 18 February 2027

B80 AERODROME/FACILITY DIRECTORY

HARRISON HOT SPRINGS BC

CAE7

REF	N49 18 17 W121 47 15 Adj S 17°E (2013) UTC-8(7) Elev 34' A5004
OPR	Village 604-796-2171 Reg
PF	B-1,2,3,5
FLT PLN	FIC Kamloops 866-WXBRIEF (Toll free within Canada) or 866-541-4101 (Toll free within Canada & USA)
SERVICES	
S	5
A/D DATA	Lake freezes occasionally Dec-Feb. Sand beach.
COMM	ATF tfc 123.2 2NM 1500 ASL
CAUTION	
	Lake rough in strong N winds. Ctc Harris crossing aprx 900 ASL across mouth of off-shore. Use dredged channel to acc



HARTLEY BAY BC

CAY4

REF	N53 25 W129 15 Adj 19°E (2013) UTC-8(7) Elev 00' A5013
OPR	TC 604-666-5420 Reg
PF	C-1
FLT PLN	FIC Kamloops 866-WXBRIEF (Toll free within Canada) or 866-541-4101 (Toll free within Canada & USA)
SERVICES	
S	7
COMM	ATF tfc 123.2 2NM 1500 ASL
CAUTION	
	Bay can be rough, watch for fishing boats.

