

FLIGHT PLAN & SITE SURVEY

RICHARD W. LEVAN AIPORT 40647 AMBERLY RD
WINGHAM

October 01, 2026



IMPORTANT NOTICE

Please ensure you have received all required authorizations prior to flight. This Site Survey was created using RPAS Wilco. The user accepts all responsibility for the accuracy of the information.

Terms & Conditions: rpaswilco.com/#tnc

Mission Information

RICHARD W. LEVAN AIPORT 40647 AMBERLY RD WINGHAM

FLIGHT DETAILS

Reference No:	MAAC-759-4813
Project Name:	WINGHAM JET CLUB
Pilot Name:	MAAC
Pilot Certificate:	
Mission Type:	VLOS
Flight Start:	October 01, 2026 02:41 AM
Flight End:	October 01, 2026 03:41 AM

LOCATION DETAILS

Flight Address:	RICHARD W. LEVAN AIPORT 40647 AMBERLY RD WINGHAM
Latitude:	43° 52' 4.30" N (43.868)
Longitude:	81° 17' 52.40" W (-81.298)
Field Elevation:	1073 ft MSL
Altitude / Radius:	400.0 ft / 926.0 m (0.5 nm)
Classification:	UNCONTROLLED
FIR / Contact:	CZYZ / 905-676-4509


REPORT CONTENTS

Site Survey • Obstacles (if available) • Nearby Aerodromes • Canadian Aviation Regulations • GFA • Aerodrome Supplements • METAR & TAF • NOTAMs • CFS

Flight Map & MODEL Details

MISSION LOCATION SURVEY

FLIGHT AREA MAP



MISSION LOCATION DETAILS

ROLE	LATITUDE	LONGITUDE
 MODEL	43° 52' 4.30" N 43.868	81° 17' 52.40" W -81.298
 Pilot		
 Payload Op.		
 Observer		

Airspace Classification

MISSION LOCATION SURVEY

AIRSPACE MAP



OVERLYING AIRSPACES

Class	Name	Floor	Ceiling
E	T616 Fixed RNAV Route	2200AGL	12500MSL
E	Southern Ontario Low Level Control Area f) [CAE]	3500MSL	18000MSL

NEAREST AERODROMES & DISTANCE FROM OPERATION

RICHARD W. LEVAN (CPR7 - AERODROME - Reg)	Lat: 43.867	Long: -81.298	0.0KM	0.0NM	SW
Operator: TYLER AND SUMMER PAPPLE: PHONE: 519-318-4224, POST: UNKNOWN, URL: www.pappleaviation.ca FIR Contact: 905-676-4509					
WINGHAM (INGLIS FIELD) (CWH5 - AERODROME - Reg)	Lat: 43.896	Long: -81.336	3.499KM	1.889NM	NW
Operator: TOM INGLIS: PHONE: 519-357-2781, POST: UNKNOWN FIR Contact: 905-676-4509					
TEESWATER (THOMPSON FIELD) (CPC6 - AERODROME - Reg)	Lat: 43.948	Long: -81.272	8.26KM	4.46NM	N
Operator: D. THOMPSON: PHONE: 519-357-5853, POST: UNKNOWN FIR Contact: 905-676-4509					
HARKES FIELD (CHF5 - AERODROME - Reg)	Lat: 43.858	Long: -81.143	11.541KM	6.232NM	E
Operator: DOUG HARKES: PHONE: 519-335-6091, POST: UNKNOWN FIR Contact: 905-676-4509					
TEESWATER (DENT FIELD) (CDF2 - AERODROME - Reg)	Lat: 43.994	Long: -81.294	13.154KM	7.103NM	N
Operator: J. DENT: PHONE: 519-901-3886, POST: UNKNOWN FIR Contact: 905-676-4509					


WINGHAM / RICHARD W. LeVAN ON

CPR7

REF	N43 52 03 W81 17 55 1SE 9°W (2013) UTC-5(4) Elev 1067' A5000	
OPR	Tyler and Summer Papple 519-318-4224 (text preferred) www.PappleAviation.ca Reg	
PF	A-5 B-6 C-1,2,3,4	
CUST	AOE/15 888-226-7277 14-22Z† Mon-Fri exc hols	
FLT PLN	FIC London 866-WXBRIEF (Toll free within Canada) or 866-541-4104 (Toll free within Canada & USA)	
SERVICES	FUEL 100LL, MG-3 A/D not attended. Self-serve, see OPR website.	
RWY DATA	Rwy 13(130°)/31(310°) 4000x75 ASPH AGN IIIA	
	RCR Opr No win maint	
LIGHTING	13-(TE ME), 31-(TE ME) ARCAL-123.0 type K	
COMM	ATF tfc 123.0 3NM 4000 ASL	
PRO	Rgt hand circuits Rwy 13 (CAR 602.96).	
CAUTION	2 silos 80 AGL NE thld Rwy 31. Numerous twrs in vic. Wildlife ocsl on rwy. Glider activity in the vicinity of A/D Sat-Sun & hol(s) Apr-Jun & Sep-Nov. Ocsl RPAS ops.	

WINGHAM (INGLIS FIELD) ON

CWH5

REF	N43 53 47 W81 20 11 1.2NW 9°W (2013) UTC-5(4) Elev 1015’ A5000	
OPR	Tom Inglis 519-357-2781 Reg PPR	
FLT PLN		
FIC	London 866-WXBRIEF (Toll free within Canada) or 866-541-4104 (Toll free within Canada & USA)	
RWY DATA	Rwy 04(036°)/22(216°) 2968x65 GRASS Thld 22 displ 650’ spring and fall only.	
RCR	Opr No win maint. Rwy soft in spring and fall, particularly at N end.	
COMM		
ATF	tfc 123.0 3NM 4000	
PRO	Rgt hand circuits Rwy 22 (CAR 602.96)	
CAUTION	Rwy elev highest in middle. Far end of rwy not vis when on thld. Two twrs 0.8NM and 1.0NM NE of A/D 1500 ASL. Ocsl wildlife on rwy. Wooded area with 50’ trees lining the first 1000’ Rwy 22. Maintain 1200 ASL over hwy on 04 apch. Wingham Airfield (CPR7) lctd 2.3NM SE of fld.	


ONTARIO

AERODROME / FACILITY DIRECTORY

TEESWATER (THOMPSON FIELD) ON


CPC6

REF	N43 56 54 W81 16 19 2.5S 9°W UTC-5(4) Elev 1000' A5000
OPR	D. Thompson 519-357-5853 Reg
PF	C-1,2,3,4,5
FLT PLN	FIC London 866-WXBRIEF (Toll free within Canada) or 866-541-4104 (Toll free within Canada & USA)
SERVICES	S 4,5,6
RWY DATA	Rwy 18(177°)/36(357°) 2450x60 GRASS
RCR	Opr No win maint. Soft in spring.
COMM	ATF tfc 122.8 5NM centred on Teeswater/Dent Field (CDF2) 2 NM N 4000 ASL
CAUTION	Hydro wires 600' S of Thld 36. Bush 500' N of Thld 18.



WROXETER / HARKES FIELD ONCHF5

REF	N43 51 27 W81 08 35 Adj SSE 9°W (2023) UTC-5(4) Elev 1115' A5000
OPR	Doug Harkes 519-335-6091 Reg PPR
FLT PLN	
FIC	London 866-WXBRIEF (Toll free within Canada) or 866-541-4104 (Toll free within Canada & USA)
SERVICES	
S	5
RWY DATA	Rwy 18(179°)/36(359°) 2600x75 GRASS
RCR	Opr No win maint. Soft in Spring.
COMM	
ATF	tfc 122.8 3NM 4000 ASL



ONTARIO

AERODROME / FACILITY DIRECTORY

TEESWATER (DENT FIELD) ON

CDF2

REF	N43 59 40 W81 17 37 Adj W 9°W UTC-5(4) Elev 1050' A5000
OPR	J. Dent 519-901-3886 Reg PPR
PF	B-1 C-2 D-3,4,5,6
FLT PLN	
FIC	London 866-WXBRIEF (Toll free within Canada) or 866-541-4104 (Toll free within Canada & USA)
SERVICES	
S	4,5,6
RWY DATA	Rwy 18(177°)/36(357°) 2500x60 GRASS
RCR	Opr Ltd win maint
COMM	
ATF	tfc 122.8 5NM 4000 ASL
CAUTION	Trees 500' N of Thld 18.

