



This certifies that MAAC has authorized **ST. JOHN'S R/C FLYERS [Club 206, Zone B]**

To operate the following categories of models: **mRPAS, RPAS**

At or from the following location: **MILLER'S POND**, 39 Beaver Creek Road, Portugal Cove-St. Philips – within 0.5 nm of **47 37' 33"N, 52 49' 28"W**

This authorization is contingent upon all members who use this site following the applicable Canadian Aviation Regulations, local laws, the club rules and the MAAC Safety Code.

MAAC provides the following:

- This site is 2.9NM from St. John's International Airport (CYJT) in Class D Control Zone controlled airspace. The grid altitude at this site is ground level.
- This site has been approved for mRPAS (sub-250gram) and RPAS operation in accordance with the approved site rules. Clear procedures in the event of a lateral or vertical flyaway outside the approved flying area must be included in club rules, with the contact information for Air Traffic Services (CYJT ATC) prominently displayed at the site. (CAR 901.15).
- All pilots responsible for RPAS operation must have an Advanced RPAS operator certificate.
- All RPAS must conform with the MAAC Safety assurance/matrix manufacturer declaration policy or another manufacturer's safety assurance/matrix manufacturer declaration.
- All pilots responsible for RPAS operation must receive individual approval from NAV CANADA using NAV DRONE for all RPAS operations regardless of altitude. Approval by NAV CANADA may be granted or be withheld day by day at their sole discretion.
- Per CAR 901.47(2), as the pilot stations are located within 3nm of an airport the club rules must comply with MAAC policy and procedure documents and must contain any additional procedures the Club deems appropriate to meet CAR 901.73 and the guidance contained in TP 14371, RPA Section 3.2.35 and 3.4.5, and which otherwise permit RPAS operation in a manner that should not interfere with aircraft operating in the established traffic pattern (CAR 901.47(1)).
- CAR compliance remains an individual responsibility.
- Any changes to club rules or procedures upon which this authorization was issued **MUST** be approved by MAAC.

This authorization is valid until the ST. JOHN'S R/C FLYERS [Club 206, Zone B] fails to renew their MAAC membership, dissolves, or otherwise does not comply with any MAAC requirements or requests.



President, MAAC

August 9th, 2025

Date